

WONUM	STATUS	STATUSDATE	WORKTYPE	DESCRIPTION
16-12936511	WAPPR	26-MAY-16	SERVICECALL	EAST WING BASEMENT MENS RESTROOM
16-12936335	CLOSE	31-MAY-16	SERVICECALL	replace the burnt-out light bulb in the east wing just before you enter the main entrance.
16-12936329	CLOSE	31-MAY-16	SERVICECALL	EW RM 200 TOO HOT
16-12936140	CLOSE	25-MAY-16	SERVICECALL	EW ROOM 200 TOO COLD
16-12935620	WAPPR	20-MAY-16	SERVICECALL	EW 2nd floor room 212 paint shop to clean up the excess paint.
16-12935591	WAPPR	19-MAY-16	SERVICECALL	EW 2nd floor room 212 need to secure and tighten the screws.
16-12935392	CLOSE	31-MAY-16	SERVICECALL	EW replace light in the east wing 2nd floor room 202
16-12935283	CLOSE	25-MAY-16	SERVICECALL	EW Colonnade Mats
16-12935197	CLOSE	18-MAY-16	SERVICECALL	EAST COLENNADE TOO HOT
16-12935152	CLOSE	24-MAY-16	SERVICECALL	electricians to replace the burnt-out light bulb in the west wing ground floor men's bathroom asap.
16-12934822	CLOSE	09-MAY-16	SERVICECALL	EW 2nd floor men's bathroom door
16-12934662	CLOSE	10-MAY-16	SERVICECALL	EW main entrance
16-12934548	WAPPR	05-MAY-16	SERVICECALL	EW / WW; Custodial Shop; see decription
16-12934516	CLOSE	10-MAY-16	SERVICECALL	EW main entrance
16-12934515	CLOSE	10-MAY-16	SERVICECALL	check this Zone 2 E - 02 the customer says it's blowing warm air
16-12934011	CLOSE	11-MAY-16	SERVICECALL	EW room 206/208 PM FCU (Carpenter/Move Shop)
16-12934009	WAPPR	03-MAY-16	SERVICECALL	EW room 206/208 PM FCU (Carpenter/Move Shop)
16-12930933	WAPPR	02-MAY-16	SERVICECALL	custodian shop to please clean all the east wing molding.
16-12930808	WAPPR	02-MAY-16	SERVICECALL	EW window well
16-12930805	WAPPR	02-MAY-16	SERVICECALL	EW Colonnade doors
16-12929200	WAPPR	28-APR-16	SERVICECALL	
16-12929198	WAPPR	28-APR-16	SERVICECALL	EW Colonnade
16-12929146	CLOSE	24-MAY-16	SERVICECALL	EW/WW; Electrical Shop; see description
16-12927675	CLOSE	28-APR-16	SERVICECALL	EW Social Office - HVAC Issues
16-12927626	CLOSE	27-APR-16	SERVICECALL	E.W. Loose Door Closure behind Theatre
16-12927603	CLOSE	28-APR-16	SERVICECALL	Check a Door Closure in the East Wing. This is behind the Theater by the FCU that goes Outside.
16-12923321	CLOSE	28-APR-16	SERVICECALL	EW/Engineer Shop; see description
16-12923129	CLOSE	27-APR-16	SERVICECALL	ladies room 2nd floor
16-12923061	CLOSE	25-APR-16	SERVICECALL	EW LB
16-12923035	CLOSE	03-MAY-16	SERVICECALL	EW/Electrical Shop; see description
16-12923019	WAPPR	19-APR-16	SERVICECALL	EW/Plumbing Shop; see decription
16-12922941	CLOSE	10-MAY-16	SERVICECALL	USSS Booth# A-2. The Condensing A/C Unit has No Power.
16-12922915	WAPPR	18-APR-16	SERVICECALL	plumbers to fix the broken tissue holder in the east wing 2nd floor ladies bathroom.
16-12922676	WAPPR	15-APR-16	SERVICECALL	plumbers to unclog / fix the leaky urinal in the east wing by room 100 Visitor's office.
16-12922502	WAPPR	14-APR-16	SERVICECALL	EW/Paint Shop; see description
16-12922445	WAPPR	13-APR-16	SERVICECALL	EW/Paint Shop; see description
16-12922361	WAPPR	13-APR-16	SERVICECALL	EW 1ST FLOOR MEN'S ROOM URINAL OVER FLOWING
16-12922274	CLOSE	10-MAY-16	SERVICECALL	EW/WW; Electrical Shop; see description
16-12922272	CLOSE	20-APR-16	SERVICECALL	EW/Move Shop; see description
16-12921893	CLOSE	10-MAY-16	SERVICECALL	EW/Electrical Shop; see description
16-12921886	WAPPR	11-APR-16	SERVICECALL	EW Outside Drain/Plumbing Shop; see description

16-12921240	CLOSE	20-APR-16	SERVICECALL	EW/Move Shop; see description
16-12921210	CLOSE	13-APR-16	SERVICECALL	EEOB/Engineer Shop; see description
16-12921112	CLOSE	06-APR-16	SERVICECALL	EW E-1-11 and E-1-12 TOO COLD
16-12918897	CLOSE	06-APR-16	SERVICECALL	engineers to lower the temperature by 2 degrees in the east wing colonnade and main entrance.
16-12918895	CLOSE	10-APR-16	SERVICECALL	EW 2nd floor
16-12918894	CLOSE	01-APR-16	SERVICECALL	EW Colonnade mats
16-12915247	CLOSE	01-APR-16	SERVICECALL	paint shop to recaulk around the sink in the east wing by the main entrance
16-12915246	CLOSE	04-APR-16	SERVICECALL	custodian shop to remove all the cleaning supplies from the
16-12915043	CLOSE	25-APR-16	SERVICECALL	EW 2nd floor
16-12914696	CLOSE	06-APR-16	SERVICECALL	EW SOS
16-12914198	CLOSE	04-APR-16	SERVICECALL	EW/Custodial Shop; see description
16-12914189	CLOSE	28-MAR-16	SERVICECALL	EW; bring up the mats from the east wing basement and lay down couple hours before the rain start
16-12914166	CLOSE	04-APR-16	SERVICECALL	carpenters to place a support to hold the FCU grill/vent
16-12914165	CLOSE	31-MAR-16	SERVICECALL	electricians to replace the burnt-out light bulb in the east wing by the landing.
16-12914161	CLOSE	31-MAR-16	SERVICECALL	electricians to replace the burnt-out light bulb in the east wing by the landing.
16-12893765	CLOSE	30-MAR-16	SERVICECALL	EW/Plumbing Shop; see description
16-12668236	CLOSE	01-APR-16	SERVICECALL	EW 2nd floor; see description
16-12668232	CLOSE	30-MAR-16	SERVICECALL	EW ground floor men's bathroom; see description
16-12668046	CLOSE	04-APR-16	SERVICECALL	EW 2nd floor ladies bathroom
16-12667171	CLOSE	31-MAR-16	SERVICECALL	EW Lower Press; replace burnt out light bulb
16-12666862	CLOSE	22-MAR-16	SERVICECALL	EW 2nd floor; see description
16-12666861	CLOSE	22-MAR-16	SERVICECALL	EW Elevator Cab; see description
16-12666806	CLOSE	22-MAR-16	SERVICECALL	EW ROOM 211B LIGHT OUT
16-12666766	CLOSE	23-MAR-16	SERVICECALL	custodian shop to clean, dust, vacuum outside/inside mats and mop the east wing colonnade.
16-12666358	CLOSE	17-MAR-16	SERVICECALL	EW Colonnade mats; see description
16-12666224	CLOSE	30-MAR-16	SERVICECALL	EW BASEMENT SQUAD ROOM SINK LEAKING
16-12666156	CLOSE	23-MAR-16	SERVICECALL	EW Colonnade Windows
16-12666155	CLOSE	23-MAR-16	SERVICECALL	EW Rm 100
16-12666154	CLOSE	01-APR-16	SERVICECALL	EW Rm 100
16-12666148	CLOSE	17-MAR-16	SERVICECALL	ZONE 2E-07 TOO HOT
16-12666041	CLOSE	23-MAR-16	SERVICECALL	EW/Custodial Shop; see description
16-12665929	CLOSE	17-MAR-16	SERVICECALL	temperature lowered 2 degrees in East Wing 212
16-12665518	CLOSE	01-APR-16	SERVICECALL	EW/Paint Shop; see decription
16-12665336	CLOSE	10-MAR-16	SERVICECALL	EW COLENNADE
16-12665335	CLOSE	28-MAR-16	SERVICECALL	movers to move all the mats down to the basement
16-12665102	CLOSE	01-APR-16	SERVICECALL	paint shop to do touch ups in the east wing main entrance doors.
16-12664952	CLOSE	04-MAR-16	SERVICECALL	EW Colonnade mats; see description
16-12662209	CLOSE	04-MAR-16	SERVICECALL	EW COLONNADE
16-12662138	CLOSE	15-MAR-16	SERVICECALL	Work Ticket Estimate Request
16-12660627	CLOSE	22-MAR-16	SERVICECALL	electricians to replace the burnt-out lights in the east wing 2nd floor landing.
16-12660514	CLOSE	22-MAR-16	SERVICECALL	EW ROOM 200 SEVERAL LIGHTS ARE OUT
16-12657493	CLOSE	29-FEB-16	SERVICECALL	sheet metal shop to install 4 kick plates in the east wing main entrance doors.

16-12387192	CLOSE	02-MAR-16	SERVICECALL	EW ROOM 200 PLEASE OPEN WINDOW
16-12386493	CLOSE	02-MAR-16	SERVICECALL	CHECK POST A-14 PEDESTRIAN GATE NOT SECURING
16-12386233	CLOSE	02-MAR-16	SERVICECALL	East Visitors EntranceTouch up or Re-finish ramp handrailNo later than 2/19/16
16-12386214	CLOSE	22-FEB-16	SERVICECALL	movers to move all the mats from the east wing colonnade to the basement tonight before 7 PM.
16-12386208	CLOSE	10-MAR-16	SERVICECALL	custodian shop to strip, wax and polish the entire colonnade on this Thursday night.
16-12384942	CLOSE	18-FEB-16	SERVICECALL	EW ZONE E2-07 AND E2-08 COLD AIR BLOWING
16-12384867	CLOSE	10-MAR-16	SERVICECALL	B-11THERE'S AN ODOR OF A DEAD ANIMAL INSIDE THE POST
16-12384208	CLOSE	04-APR-16	SERVICECALL	EW
16-12384207	CLOSE	29-FEB-16	SERVICECALL	East/West Wing Gover's Dinner/Canada Visit
16-12384113	CLOSE	31-MAR-16	SERVICECALL	paint shop to paint over the eye-hook.
16-12384101	CLOSE	29-FEB-16	SERVICECALL	electricians to replace the burnt-out light bulb in the east wing ground floor men's bathroom.
16-12383492	CLOSE	10-FEB-16	SERVICECALL	EW ROOM 212 IS TOO HOT PLEASE ADJUST TEMP
16-12383061	CLOSE	31-MAR-16	SERVICECALL	patch/paint east wing colonnade just above the steps by the column by the ladies bathroom steps.
16-12383060	CLOSE	31-MAR-16	SERVICECALL	patch/paint east wing colonnade above the ceiling by the ladies bathroom steps and the USSS desk.
16-12383058	CLOSE	31-MAR-16	SERVICECALL	patch/paint the eye hooks which are in the east wing by the colonnade above the door and the window.
16-12383051	CLOSE	30-MAR-16	SERVICECALL	EW WATER FOUNTAIN NEAR G-3 POST NOT WORKING
16-12376507	CLOSE	02-MAR-16	SERVICECALL	EW/Carpenter Shop; see decription
16-12375640	CLOSE	03-MAR-16	SERVICECALL	EW/Electrical Shop; see description
16-12375467	CLOSE	27-APR-16	SERVICECALL	carpenters to fix and secure the window latch in the east wing.
16-12372942	CLOSE	04-FEB-16	SERVICECALL	EW ROOM 100 TOO COLD
16-12169025	CLOSE	28-JAN-16	SERVICECALL	EW Colonnade/Move Shop; see description
16-12168876	CLOSE	02-MAR-16	SERVICECALL	
16-12168315	WAPPR	20-JAN-16	SERVICECALL	EW/Elevator Shop; see description
16-12167526	CLOSE	29-FEB-16	SERVICECALL	EW 2nd floor/Electrical Shop; see description
16-12166769	CLOSE	25-JAN-16	SERVICECALL	EW/Engineer Shop/Rm. 100; no heat zone 5,6
16-12166509	CLOSE	30-MAR-16	SERVICECALL	plumbers to fix the leak in the men's restroom on the East Wing 2nd floor.
15-12164733	CLOSE	11-JAN-16	SERVICECALL	To Check a Water Leak / Alarm in the E.W. in the Colonnade on FCU# 3605.
15-12163754	CLOSE	12-JAN-16	SERVICECALL	EW. Please have the Paint shop perform touch ups on the arch in the colonnade.
15-12160512	CLOSE	11-JAN-16	SERVICECALL	EW / WW lites burnt-out
16-12936550	CLOSE	31-MAY-16	SERVICECALL	WWNM
16-12936545	CLOSE	31-MAY-16	SERVICECALL	WW ZONE COS TURN UP 1 DEGREE
16-12936508	CLOSE	03-JUN-16	SERVICECALL	WW Rm 120
16-12936506	CLOSE	31-MAY-16	SERVICECALL	WW Rm 120
16-12936501	CLOSE	31-MAY-16	SERVICECALL	WW 2nd floor room 208
16-12936486	CLOSE	31-MAY-16	SERVICECALL	please dust / vacuum all the office space.
16-12936348	CLOSE	31-MAY-16	SERVICECALL	WW 2ND FLOOR RM 210 NEED WD40 FOR DOOR
16-12936166	CLOSE	24-MAY-16	SERVICECALL	custodian shop to please clean / vacuum the entire suite

16-12936143	CLOSE	31-MAY-16	SERVICECALL	electricians to replace the burnt-out light bulb in the west wing ground floor men's bathroom.
16-12936039	CLOSE	31-MAY-16	SERVICECALL	WW/Press Briefing Rm, ABC Booth; repair broken door handel
16-12935749	CLOSE	24-MAY-16	SERVICECALL	Check a Alarm in the W.W. on Crac Unit# 1 in the Press Area. - Assign to the 4 to 12 Shift Engineers
16-12935747	CLOSE	31-MAY-16	SERVICECALL	WW Press Briefing
16-12935622	CLOSE	24-MAY-16	SERVICECALL	WW 1st floor women's bathroom
16-12935506	WAPPR	29-JUN-16	SERVICECALL	W.W. Navy Mess Grill / Filter Rack/Sheet Metal Shop
16-12935481	CLOSE	24-MAY-16	SERVICECALL	WW ground floor NM; see description
16-12935417	CLOSE	18-MAY-16	SERVICECALL	ZONE 1W-39 TOO COLD
16-12935385	CLOSE	31-MAY-16	SERVICECALL	WW/OOO 1ST FLOOR; see description
16-12935199	CLOSE	18-MAY-16	SERVICECALL	ZONE 1W-39 TURN DOWN 3 DEGREES
16-12935196	CLOSE	18-MAY-16	SERVICECALL	ZONE PR1 , PR2, PR3, PR4
16-12935178	CLOSE	18-MAY-16	SERVICECALL	PRES SEC ZONE INCREASE TEMP BY 1 DEGREE
16-12935109	CLOSE	18-MAY-16	SERVICECALL	turn off the air curtain tonight at 9 : 00 pm and turn it back on on Friday night at 9 : 00 pm.
16-12935102	CLOSE	24-MAY-16	SERVICECALL	WW 1st floor men's bathroom
16-12935090	CLOSE	17-MAY-16	SERVICECALL	electricians to remove the old plate and the painters fill the open hole and patch paint.
16-12935089	CLOSE	24-MAY-16	SERVICECALL	electricians to remove the old plate and the painters fill the open hole and patch paint.
16-12935077	CLOSE	13-MAY-16	SERVICECALL	This ticket is for the locksmith to tighten the loose door handle leading to OOO.
16-12934997	CLOSE	17-MAY-16	SERVICECALL	WW ground floor
16-12934955	CLOSE	13-MAY-16	SERVICECALL	replace the old handicap push plates in the west wing by the main entrance ground floor.
16-12934922	CLOSE	13-MAY-16	SERVICECALL	To Check a Smell in the W.W. Zone# GW-11. - Assign to the 4 to 12 Shift Engineers
16-12934920	CLOSE	24-MAY-16	SERVICECALL	WW ground floor NM
16-12934918	CLOSE	31-MAY-16	SERVICECALL	WW ground floor NM
16-12934848	CLOSE	25-MAY-16	SERVICECALL	WW VIP Lobby
16-12934831	CLOSE	24-MAY-16	SERVICECALL	electricians to replace the burnt-out light bulb in the west wing ground floor men's bathroom.
16-12934757	CLOSE	13-MAY-16	SERVICECALL	PLEASE MAKE SURE VP FIRE PLACE IS CLEAN AND RESTOCK
16-12934708	CLOSE	13-MAY-16	SERVICECALL	engineers to check RO system in the West wing , contact Robert Byrd for details.
16-12934674	CLOSE	17-MAY-16	SERVICECALL	WW by W - 16
16-12934543	CLOSE	24-MAY-16	SERVICECALL	EW / WW; Custodial Shop; see decription
16-12934534	CLOSE	10-MAY-16	SERVICECALL	WW ground floor men's bathroom; see description
16-12934517	CLOSE	17-MAY-16	SERVICECALL	WW ground floor
16-12934476	CLOSE	05-MAY-16	SERVICECALL	landscape shop to treat for Pest issues in the west wing ground floor G - 74 NSC suite.
16-12934402	CLOSE	13-MAY-16	SERVICECALL	lower press behind briefing room too cold
16-12934063	CLOSE	13-MAY-16	SERVICECALL	TURN UP 2 DEGREES ZONE 1W-39
16-12934039	CLOSE	06-MAY-16	SERVICECALL	WW 1st / ground
16-12934013	CLOSE	13-MAY-16	SERVICECALL	WW room 202/Engineer Shop; see description
16-12933937	CLOSE	24-MAY-16	SERVICECALL	WW/Electrical Shop; see description
16-12933315	CLOSE	24-MAY-16	SERVICECALL	WW/EW
16-12930937	CLOSE	06-MAY-16	SERVICECALL	WW 1st floor
16-12930935	CLOSE	24-MAY-16	SERVICECALL	WW 1st floor
16-12930930	CLOSE	06-MAY-16	SERVICECALL	WW
16-12930829	CLOSE	06-MAY-16	SERVICECALL	WW ground floor

16-12930809	CLOSE	13-MAY-16	SERVICECALL	engineers to clean all the east and west wings supply and return vents.
16-12930804	CLOSE	10-MAY-16	SERVICECALL	WW 1st floor by Roosevelt room bathrooms
16-12929201	CLOSE	05-MAY-16	SERVICECALL	plumbers to unclog the drain in the west wing navy mess kitchen under the sink by the dishwasher.
16-12929137	CLOSE	24-MAY-16	SERVICECALL	WW LADIES ROOM BEHIND PRESS BRIEFING ROOM LIGHT IS OUT
16-12929058	CLOSE	31-MAY-16	SERVICECALL	WW OVAL RAISE TEMP BY 2 DEGREES
16-12929056	CLOSE	28-APR-16	SERVICECALL	RAISE TEMP BY 2 DEGREES
16-12928980	CLOSE	28-APR-16	SERVICECALL	Raise the Temperature Set Point up 2 Degrees in the W.W. Zone# 2W-51 and 2W-55
16-12927818	CLOSE	28-APR-16	SERVICECALL	WW ground floor NM; see description
16-12927804	CLOSE	28-APR-16	SERVICECALL	PR-1,PR-2,PR-3, AND PR-4 LOWER 2 DEGREES
16-12927801	CLOSE	28-APR-16	SERVICECALL	ZONE W2-41 TURN UP 2 DEGREES
16-12927730	CLOSE	28-APR-16	SERVICECALL	W.W. Executive Dining Room.
16-12927729	CLOSE	05-MAY-16	SERVICECALL	W.W. Executive Dining Room. The Leak is coming from a Steam Coil.
16-12927727	CLOSE	28-APR-16	SERVICECALL	ZONE W2-42 TOO HOT
16-12927723	CLOSE	28-APR-16	SERVICECALL	Check a Leak in the W.W. Navy Mess Executive Dining Room. - Assign to the 4 to 12 Shift Engineers
16-12927722	CLOSE	28-APR-16	SERVICECALL	Check a Noise in the W.W. on the Navy Mess AH's. - Assign to the 4 to 12 Shift Engineers
16-12927715	CLOSE	05-MAY-16	SERVICECALL	plumbers to fix the loose flush handle in the west wing by Roosevelt room ladies bathroom.
16-12927705	CLOSE	24-MAY-16	SERVICECALL	WW VIP LOBBY
16-12927624	CLOSE	03-MAY-16	SERVICECALL	paint shop to patch touch up paint in the west wing by the men's bathroom by Roosevelt room.
16-12927517	CLOSE	06-MAY-16	SERVICECALL	painters to paint the entire men's bathroom in the west wing by the Roosevelt room.
16-12927515	CLOSE	05-MAY-16	SERVICECALL	carpenters to refinish the ground floor west wing thresholds by the hallway NSA.
16-12927494	CLOSE	03-MAY-16	SERVICECALL	electricians to take the light bulbs out from over G - 74 Meg's desk.
16-12923370	CLOSE	03-MAY-16	SERVICECALL	There's a dead mouse in the west wing 2nd floor VJ'S office
16-12923369	CLOSE	28-APR-16	SERVICECALL	Touch up/paint Oval Dining Pantry
16-12923368	CLOSE	28-APR-16	SERVICECALL	Small paint nick on the interior side chair rail portion of the door by Post E - 6
16-12923367	CLOSE	28-APR-16	SERVICECALL	Touch up/paint the door from the Outer Oval Office into the Oval Office
16-12923366	CLOSE	28-APR-16	SERVICECALL	Touch up/paint the patio door from the Rose Garden patio into the Oval Office
16-12923359	CLOSE	04-MAY-16	SERVICECALL	WW/Move Shop; see description
16-12923350	CLOSE	28-APR-16	SERVICECALL	WW Oval/Paint Shop; see description
16-12923347	CLOSE	03-MAY-16	SERVICECALL	WW OOO/Electrical Shop; see description
16-12923319	CLOSE	28-APR-16	SERVICECALL	WW/Engineer Shop; see description
16-12923261	CLOSE	22-APR-16	SERVICECALL	To Raise the Temperature 1 Degrees from the Occupant Request.
16-12923259	CLOSE	21-APR-16	SERVICECALL	Engineers to check all the AHU. BAD SMELL
16-12923258	CLOSE	24-MAY-16	SERVICECALL	To please clean all the trash cans in the west wing.
16-12923192	CLOSE	20-APR-16	SERVICECALL	
16-12923089	CLOSE	03-MAY-16	SERVICECALL	Nordic State Visit WW Walk Through 4/8/Electrical Shop

16-12923087	CLOSE	20-APR-16	SERVICECALL	Nordic State Visit WW Walk Through 4/8
16-12923086	CLOSE	05-MAY-16	SERVICECALL	Nordic State Visit WW Walk Through 4/8
16-12923062	CLOSE	20-APR-16	SERVICECALL	temperature in zone 2W-41 raised 2 degrees
16-12923050	CLOSE	05-MAY-16	SERVICECALL	WW/Plumbing Shop; see description
16-12923016	CLOSE	06-MAY-16	SERVICECALL	paint shop to touch up by the Oval pantry and hallway
16-12923004	CLOSE	19-APR-16	SERVICECALL	WW/Engineer Shop; see description
16-12922883	CLOSE	19-APR-16	SERVICECALL	To Check the W.W. Sit Room A/C not Working. - Assign to the 4 to 12 Shift Engineers
16-12922761	CLOSE	03-MAY-16	SERVICECALL	WW VP OUTER OFFICE THERE ARE SEVERAL LIGHTS OUT
16-12922570	CLOSE	20-APR-16	SERVICECALL	Nordic State Visit/WW Walkthrough 4/8; see description
16-12922569	CLOSE	03-MAY-16	SERVICECALL	WW/Electrical Shop; see description
16-12922551	CLOSE	19-APR-16	SERVICECALL	Nordic State Visit; WW Walkthrough 4/8; see description
16-12922533	CLOSE	03-MAY-16	SERVICECALL	WW/Paint Shop; see description
16-12922505	CLOSE	24-MAY-16	SERVICECALL	Nordic State Visit; WW Walkthrough 4/8; see description
16-12922273	CLOSE	10-MAY-16	SERVICECALL	EW/WW; Electrical Shop; see description
16-12922271	CLOSE	24-MAY-16	SERVICECALL	WW 1st floor women's and men's bathrooms
16-12922177	CLOSE	18-APR-16	SERVICECALL	WW 1st floor CoS; see description
16-12922154	CLOSE	28-APR-16	SERVICECALL	WW/Paint Shop; see description
16-12922140	CLOSE	10-MAY-16	SERVICECALL	WW/Electrical Shop; see description
16-12921915	CLOSE	31-MAY-16	SERVICECALL	WW 2nd floor room 221; see description
16-12921909	CLOSE	10-MAY-16	SERVICECALL	WW/Electrical Shop; see description
16-12921899	CLOSE	28-APR-16	SERVICECALL	WW/Carpenter Shop; see description
16-12921663	CLOSE	12-APR-16	SERVICECALL	WW LOWER PRESS KEY BROKEN OFF DESK
16-12921221	CLOSE	06-APR-16	SERVICECALL	WH South Park Ant Issue
16-12921208	CLOSE	10-APR-16	SERVICECALL	WW/EW-Electrical Shop; see description
16-12921207	CLOSE	10-APR-16	SERVICECALL	WW/Electrical Shop; see description
16-12921147	CLOSE	10-APR-16	SERVICECALL	electricians to replace the burnt-out lights in the west wing Press Secretary's Suites.
16-12920357	CLOSE	05-APR-16	SERVICECALL	WW/Landscape Shop; see description
16-12920338	CLOSE	05-APR-16	SERVICECALL	landscape shop to take care of this request asap flag came loose. This is on the west executive Ave.
16-12918930	CLOSE	13-APR-16	SERVICECALL	custodian shop to take care of this coffee spill in the west wing by W - 16 ground floor.
16-12915264	CLOSE	01-APR-16	SERVICECALL	custodian shop to please clean/wipe down all the baseboards in the east and west wings.
16-12915262	CLOSE	10-APR-16	SERVICECALL	electricians to clean all the light fixtures in the east and west wings hallways.
16-12915254	CLOSE	01-APR-16	SERVICECALL	WW Oval hallway
16-12915252	CLOSE	01-APR-16	SERVICECALL	landscape shop to fill the open hole in the west wing room 217
16-12915052	CLOSE	31-MAR-16	SERVICECALL	To Secure and Reattach a Filter Door on the W.W. AH# 2. - Assign to the 4 to 12 Shift Engineers
16-12915051	CLOSE	31-MAR-16	SERVICECALL	To Check the W.W. AH# 2 Drain System. - Assign to the 4 to 12 Shift Engineers
16-12915050	CLOSE	10-APR-16	SERVICECALL	Light
16-12915044	CLOSE	28-APR-16	SERVICECALL	WW Trash Can
16-12914970	CLOSE	01-APR-16	SERVICECALL	WW VIP Lobby door
16-12914768	CLOSE	05-APR-16	SERVICECALL	SHEET METAL SHOP
16-12914695	CLOSE	31-MAR-16	SERVICECALL	WW OOO
16-12914522	CLOSE	01-APR-16	SERVICECALL	WW Roosevelt room; see description
16-12914325	CLOSE	06-APR-16	SERVICECALL	engineers to check and test ro system

16-12914318	CLOSE	28-MAR-16	SERVICECALL	OOO
16-12914191	CLOSE	31-MAR-16	SERVICECALL	engineers to remove the thermometer which is next to the Zone sensor.
16-12914190	CLOSE	06-APR-16	SERVICECALL	engineers to remove the thermometer which is next to the Zone sensor.
16-12914188	CLOSE	01-APR-16	SERVICECALL	WW room 210
16-12914186	CLOSE	30-MAR-16	SERVICECALL	WW NM; fix the leaky trap in the west wing navy mess kitchen under the sink
16-12898654	CLOSE	10-APR-16	SERVICECALL	EW / WW; see description
16-12894653	CLOSE	05-APR-16	SERVICECALL	WW VIP Lobby/Carpenter Shop; see description
16-12668273	CLOSE	01-APR-16	SERVICECALL	WW Oval pantry
16-12668238	CLOSE	23-MAR-16	SERVICECALL	WW Oval pantry; see description
16-12668225	CLOSE	30-MAR-16	SERVICECALL	WW 2nd floor; fill the open hole with steelwool room 218 it's the back big office on your left
16-12668060	CLOSE	31-MAR-16	SERVICECALL	W 1 tunnel; epoxy the 001 and 002 elevator landings in the W 1 tunnel.
16-12668050	CLOSE	31-MAR-16	SERVICECALL	W 1 Tunnelk; epoxy floor the ramp in the the W1 tunnel
16-12667818	CLOSE	22-MAR-16	SERVICECALL	carpenters to look at our ceiling one of the tiles looks pretty low and coming lose.
16-12667298	CLOSE	17-MAR-16	SERVICECALL	lower the temperature in the press area that is behind the press briefing room
16-12667232	CLOSE	17-MAR-16	SERVICECALL	lower the temp in the press secretary's WW office by 2 degrees (Press Sec)?
16-12666977	CLOSE	23-MAR-16	SERVICECALL	door that's leading to the study from the Oval Office.
16-12666864	CLOSE	10-APR-16	SERVICECALL	EW/ WW; remove all the insect light bulbs from the east and west wings
16-12666863	CLOSE	22-MAR-16	SERVICECALL	WW/ replace the burnt-out light bulb in the west wing ground floor by Press Secretary's office
16-12666846	CLOSE	22-MAR-16	SERVICECALL	WW VIP Lobby door
16-12666825	CLOSE	23-MAR-16	SERVICECALL	WW 2ND FLOOR SEEN MOUSE
16-12666768	CLOSE	17-MAR-16	SERVICECALL	WW general area too hot an 1W-39 is too hot
16-12666767	CLOSE	17-MAR-16	SERVICECALL	Turn off a/c today between 2:25 pm - 3:00 pm today for tapping
16-12666758	CLOSE	31-MAR-16	SERVICECALL	replace the bulb which is too big for the light fixture, it's sticking out as you can see it.
16-12666753	CLOSE	22-MAR-16	SERVICECALL	electricians to replace check out the street light in the west executive Ave is pink in color.
16-12666748	CLOSE	31-MAR-16	SERVICECALL	WW/EW Changing Clocks
16-12666593	CLOSE	17-MAR-16	SERVICECALL	3/9/16
16-12666591	CLOSE	17-MAR-16	SERVICECALL	3/9/16
16-12666587	CLOSE	15-MAR-16	SERVICECALL	3/10/16
16-12666585	CLOSE	15-MAR-16	SERVICECALL	3/10/16
16-12666367	CLOSE	23-MAR-16	SERVICECALL	WW/EW- Custodial Shop; see description
16-12666253	CLOSE	22-MAR-16	SERVICECALL	Disable and Turn Off the Fan on the Air Curtain in the W.W.
16-12666251	CLOSE	17-MAR-16	SERVICECALL	Engineers to Clean the Air Vents in the W.W. Roosevelt Room. - Assign to the 4 to 12 Shift Engineers
16-12666245	CLOSE	17-MAR-16	SERVICECALL	temperature permanently lowered 2 degrees in West Wing zones PR1, PR2, PR3, and PR4
16-12666140	CLOSE	28-MAR-16	SERVICECALL	WW; Elevator Shop; see description
16-12665896	CLOSE	23-MAR-16	SERVICECALL	Mason shop replace the treads on the West Exec stairs leading up to the VIP entry.
16-12665862	CLOSE	15-MAR-16	SERVICECALL	
16-12665861	CLOSE	17-MAR-16	SERVICECALL	temperature lowered by 2 degrees in zone COS in the West Wing?

16-12665656	CLOSE	23-MAR-16	SERVICECALL	fix the leaky copper drian union under the sink in the kitchen navy mess.
16-12665655	CLOSE	14-MAR-16	SERVICECALL	WW 2ND FLOOR ZONE W2-42 DOOR KNOB FELL OFF
16-12665636	CLOSE	23-MAR-16	SERVICECALL	WW PRESS LOBBY ORDER WATER FOUNTIAN
16-12665338	CLOSE	14-MAR-16	SERVICECALL	WW 2ND FLOOR ROOM 208 SET TRAPS
16-12665324	CLOSE	20-APR-16	SERVICECALL	POST A-4 THERE IS AN INFESTATION OF ANTS INSIDE POST
16-12665323	CLOSE	14-MAR-16	SERVICECALL	WW 2nd floor RM 208
16-12665322	CLOSE	17-MAR-16	SERVICECALL	WW 2nd floor RM 208
16-12665321	CLOSE	01-APR-16	SERVICECALL	paint shop to get the paint off the door hardwares as you see in the picture.
16-12665105	CLOSE	09-MAR-16	SERVICECALL	West Wing 213
16-12665103	CLOSE	22-MAR-16	SERVICECALL	WW 2nd floor room 213
16-12665097	CLOSE	31-MAR-16	SERVICECALL	WW LOWER PRESS BASEMENT BOOTH VOA LIGHT OUT
16-12664958	CLOSE	22-MAR-16	SERVICECALL	WW Oval Office
16-12664954	CLOSE	14-MAR-16	SERVICECALL	WW 2nd floor men's bathroom
16-12664839	CLOSE	23-MAR-16	SERVICECALL	engineers to change the filters on the unit in ET 4
16-12664764	CLOSE	09-MAR-16	SERVICECALL	WW/Elevator Shop; see description
16-12664763	CLOSE	19-APR-16	SERVICECALL	WW/Elevator Shop; see description
16-12664731	CLOSE	03-MAR-16	SERVICECALL	WW/Elevator Shop; see description
16-12664716	CLOSE	08-MAR-16	SERVICECALL	Look for a Mouse in the W.W. in Zone# 2W-41 (Room# 217A). - Assign to the 4 to 12 Shift Engineers
16-12664711	CLOSE	08-MAR-16	SERVICECALL	Look for a Mouse in the W.W. in Zone# 2W-41 (Room# 215). - Assign to the 4 to 12 Shift Engineers
16-12658859	CLOSE	14-MAR-16	SERVICECALL	occasionally has little visitors that set off the motion sensors in the ceiling after hours
16-12656706	CLOSE	14-MAR-16	SERVICECALL	WW 2ND FL; Dead mouse
16-12656569	CLOSE	08-MAR-16	SERVICECALL	Check the W.W. Press Area for a Ceiling Water Leak
16-12656568	CLOSE	08-MAR-16	SERVICECALL	Temperature in the W.W. for Zone# 13 and Zone# 14. - Assign to the 4 to 12 Shift
16-12654056	CLOSE	03-MAR-16	SERVICECALL	carpenters to fix /secure the loose drinking water fountain
16-12646307	CLOSE	03-MAR-16	SERVICECALL	WW Basement Leak (towards Mechanical Rm. Door)
16-12626739	CLOSE	08-MAR-16	SERVICECALL	The set point in zone 2W-43 lowered by 2 degrees? This is on the 2nd Floor of the West Wing.
16-12387534	CLOSE	29-FEB-16	SERVICECALL	WW/Electrical Shop; see description
16-12387470	CLOSE	03-MAR-16	SERVICECALL	WW/Electrical Shop; see description
16-12387355	CLOSE	14-MAR-16	SERVICECALL	custodian shop to please fill all the empty umbrella bags in the east and west wings.
16-12387354	CLOSE	31-MAR-16	SERVICECALL	paint shop to patch touch up paint in the west wing Oval pantry.
16-12387351	CLOSE	08-MAR-16	SERVICECALL	engineers to check Ro system, contact robert byrd for details
16-12387336	CLOSE	29-FEB-16	SERVICECALL	electricians to replace the burnt-out lights in the west wing ground floor by ladies bathroom
16-12386905	CLOSE	29-FEB-16	SERVICECALL	carpenters to replace the short ceiling tile in the west wing by E -10 post.
16-12386904	CLOSE	29-FEB-16	SERVICECALL	WW OOO
16-12386558	CLOSE	08-MAR-16	SERVICECALL	To Check a Noise in the W.W. VIP Lobby Area. - Assign to the 4 to 12 Shift Engineers

16-12386404	CLOSE	04-MAR-16	SERVICECALL	carpenters to look at this thrush hold and see if you can replace or touch up asap.
16-12386399	CLOSE	30-MAR-16	SERVICECALL	plumbers to replace the broken sink in the west wing ground floor men's bathroom.
16-12386355	CLOSE	08-MAR-16	SERVICECALL	WW VIP LOBBY RAISE TEMP
16-12386245	CLOSE	17-MAR-16	SERVICECALL	REPAIRS WW/EW
16-12386244	CLOSE	31-MAR-16	SERVICECALL	GroundWest Wing West Executive Entrance
16-12386243	CLOSE	03-MAR-16	SERVICECALL	REPAIRS WW/EW
16-12386242	CLOSE	23-FEB-16	SERVICECALL	WW East colonnade entrancePost E10Touch up large wood desk
16-12386241	CLOSE	23-FEB-16	SERVICECALL	WW Upper LevelCredenza outside OOOtop has significant water stain
16-12386240	CLOSE	23-FEB-16	SERVICECALL	WW lower level and Upper levelsHand rails (stairs and top of stairs)
16-12386239	CLOSE	03-MAR-16	SERVICECALL	WW lower levelRoom W16Touch up wooden entry doors (both sides)
16-12386238	CLOSE	09-MAR-16	SERVICECALL	GroundNavy Mess areaReplace wood threshold strip
16-12386237	CLOSE	04-MAR-16	SERVICECALL	GroundWest Wing West Executive Entrance
16-12386236	CLOSE	03-MAR-16	SERVICECALL	GroundWest Wing West Executive Entrance
16-12386222	CLOSE	14-MAR-16	SERVICECALL	paint shop and the custodial shop to remove the glass from the VIP Lobby desk top
16-12386219	CLOSE	23-FEB-16	SERVICECALL	paint shop and the custodial shop to remove the glass from the VIP Lobby desk top
16-12386217	CLOSE	08-MAR-16	SERVICECALL	engineers to check out the supply /return vents in
16-12386215	CLOSE	14-MAR-16	SERVICECALL	custodian shop to deep clean and polish all the brass handles
16-12386211	CLOSE	08-MAR-16	SERVICECALL	engineers to clean all the supply /return vents in the west wing ground and 1st floors asap.
16-12386178	CLOSE	18-FEB-16	SERVICECALL	turn the temperature down in 1W-39 by 1 degree
16-12386003	CLOSE	23-FEB-16	SERVICECALL	WW/Paint Shop; see description
16-12385945	CLOSE	23-FEB-16	SERVICECALL	WW E -10 post
16-12385756	CLOSE	18-FEB-16	SERVICECALL	carpenters to fix the broken door closer. This is in the west wing ground floor by E -1 post.
16-12385255	CLOSE	29-FEB-16	SERVICECALL	electricians to support the contractor fixing the carpet issue in the west wing OOO
16-12385250	CLOSE	18-FEB-16	SERVICECALL	ROOSEVELT ROOM TURN UP 4 DEGREES
16-12385245	CLOSE	23-FEB-16	SERVICECALL	To patch touch up paint in the west wing by W-16
16-12385241	CLOSE	23-FEB-16	SERVICECALL	paint shop to patch touch up paint in the west wing by the main entrance door way.
16-12384953	CLOSE	14-MAR-16	SERVICECALL	WW 2ND FLOOR ZONE 2W-42 SEEN A RAT OR A LARGE MOUSE
16-12384901	CLOSE	04-MAR-16	SERVICECALL	paint shop to patch touch up paint in the west wing by the Navy mess hallway ground floor.
16-12384897	CLOSE	04-MAR-16	SERVICECALL	paint shop to patch touch up paint in the west wing by the ladies bathroom ground floor.
16-12384747	CLOSE	23-FEB-16	SERVICECALL	Either clean or replace the brass kick plate
16-12384746	CLOSE	23-MAR-16	SERVICECALL	there is a deep gouge in the door jamb
16-12384745	CLOSE	23-FEB-16	SERVICECALL	Paint touch ups needed on the mantel in the private dining room (GSA)
16-12384744	CLOSE	23-FEB-16	SERVICECALL	Paint touch ups needed on the two pediments above the two doors in the Oval Office (GSA)
16-12384739	CLOSE	23-FEB-16	SERVICECALL	WW ground floor
16-12384209	CLOSE	29-FEB-16	SERVICECALL	WW ground floor entrance lobby
16-12384111	CLOSE	23-FEB-16	SERVICECALL	paint shop to patch / touch up paint in the west wing ground and 1st floor hallways baseboard.

16-12384110	CLOSE	23-FEB-16	SERVICECALL	paint shop to patch / touch up paint in the west wing by the Roosevelt room entrance.
16-12384108	CLOSE	23-FEB-16	SERVICECALL	paint shop to recaulk around the commode.
16-12383066	CLOSE	04-MAR-16	SERVICECALL	WW Oval Office door
16-12383064	CLOSE	04-MAR-16	SERVICECALL	patch/paint west wing ground floor by the FCU entrance by the canopy.
16-12383063	CLOSE	23-FEB-16	SERVICECALL	patch/paint the west wing ground floor by the main entrance door way under the canopy.
16-12383062	CLOSE	23-FEB-16	SERVICECALL	paint shop to patch touch up paint in the west wing Oval pantry.
16-12382799	CLOSE	29-FEB-16	SERVICECALL	WW NAVY MESS REPAIR OUTLET
16-12376585	CLOSE	18-FEB-16	SERVICECALL	Can the temp in 1W-39 be increased by 2 degrees
16-12375619	CLOSE	29-FEB-16	SERVICECALL	WW/Electrical Shop; see description
16-12375611	CLOSE	29-FEB-16	SERVICECALL	WW/Electrical Shop; see description
16-12375605	CLOSE	23-MAR-16	SERVICECALL	WW/Oval Office/Paint Shop; see description
16-12375602	CLOSE	04-FEB-16	SERVICECALL	WW/Carpenter Shop; see description
16-12375556	CLOSE	23-MAR-16	SERVICECALL	WW/Mason Shop; see description
16-12375538	CLOSE	03-MAR-16	SERVICECALL	WW 2nd Fl Men's bathroom
16-12375535	CLOSE	23-MAR-16	SERVICECALL	WW/Paint Shop; see description
16-12375466	CLOSE	23-MAR-16	SERVICECALL	patch / touch up around the light fixtures in the west wing ground floor by the elevator.
16-12375465	CLOSE	29-FEB-16	SERVICECALL	replace several burnt-out lights in the west wing office next to the Oval Office pantry. Room 120
16-12375459	CLOSE	10-FEB-16	SERVICECALL	Check a Water Leak in the W.W. Room# 202 / Zone# 2W-58. - Assign to the 4 to 12 Shift Engineers
16-12375369	CLOSE	29-FEB-16	SERVICECALL	electricians to clean the hanging globe lamp in the west wing OOO needs to be cleaned.
16-12375211	CLOSE	23-FEB-16	SERVICECALL	paint shop to recaulk the ladies bathroom sink in the west wing by Roosevelt room.
16-12374787	CLOSE	01-FEB-16	SERVICECALL	WW 2nd floor CoS
16-12372605	CLOSE	04-FEB-16	SERVICECALL	To Check a FCU Leak in the W.W. Room# 202, Zone# 2W-58
16-12372167	CLOSE	18-FEB-16	SERVICECALL	engineers to check Ro system in W1, contact robert byrd for details
16-12369912	CLOSE	04-FEB-16	SERVICECALL	WW NAVY MESS
16-12369911	CLOSE	23-MAR-16	SERVICECALL	paint shop to patch around the light fixtures in the west wing by the elevator on the ground floor.
16-12169047	CLOSE	23-FEB-16	SERVICECALL	paint shop to check this out and see if you want to redo or just paint over it.
16-12169028	CLOSE	29-FEB-16	SERVICECALL	WW/Electrical Shop; see description
16-12168976	CLOSE	28-JAN-16	SERVICECALL	POST B4 PEDESTRAIN GATE NOT LOCKING
16-12168968	CLOSE	25-JAN-16	SERVICECALL	Lower the Zone Temperature in the W.W. Zone# 1W-29. - Assign to the 4 to 12 Shift Engineers
16-12168964	CLOSE	25-JAN-16	SERVICECALL	W.W. Press Briefing Area Temperature in various Spaces. - Assign to the 4 to 12 Shift Engineers
16-12168960	CLOSE	04-FEB-16	SERVICECALL	To Drain and Check the Hot Water System of the W.W. - Assign to the 4 to 12 Shift Engineers
16-12168882	CLOSE	25-JAN-16	SERVICECALL	lower press office increase their office temperature to working temperature to 70 degrees.
16-12168880	CLOSE	23-FEB-16	SERVICECALL	

16-12168558	CLOSE	25-JAN-16	SERVICECALL	To Adjust the W.W. Upper Press area Offices Temperature Up on AH# 3
16-12168364	CLOSE	29-FEB-16	SERVICECALL	electricians to replace the burnt-out lights in the west wing 1st floor VPS bathroom
16-12168352	CLOSE	03-MAR-16	SERVICECALL	WW LOBBY LADIES ROOM TOILET CLOG
16-12168335	CLOSE	04-MAR-16	SERVICECALL	WW/Mason Shop; see description
16-12167985	CLOSE	21-JAN-16	SERVICECALL	WW Cabinet Room
16-12167979	CLOSE	25-JAN-16	SERVICECALL	To Clean Up some Broken Glass around the South West USSS Booth.
16-12167532	CLOSE	25-JAN-16	SERVICECALL	WW Lower Press Too Cold
16-12167523	CLOSE	19-JAN-16	SERVICECALL	WW 1st floor/Lock Shop; see description
16-12167514	CLOSE	25-JAN-16	SERVICECALL	WW FAN NEEDS TO BE TURNED OFF
16-12167506	CLOSE	25-JAN-16	SERVICECALL	Can the temperature in 1W-PR1, PR2, PR3, and PR4 be increased by 2 degrees
16-12167229	CLOSE	20-JAN-16	SERVICECALL	This ticket is for the carpenters to cut down the apron over the refrigerator in the west wing.
16-12166975	CLOSE	29-FEB-16	SERVICECALL	WW 2nd floor burnt-out lights
16-12166845	CLOSE	25-JAN-16	SERVICECALL	To Adjust the Temperature in the W.W. Upper Press Area. Zone# TU101.
16-12166840	CLOSE	25-JAN-16	SERVICECALL	temperature lowered 2 degrees in Zone 1W-30
16-12166838	CLOSE	25-JAN-16	SERVICECALL	plumbers to unclog the men's bathroom 2nd floor west wing sink,
16-12166543	CLOSE	20-JAN-16	SERVICECALL	carpenters to look at the thresholds in Roosevelt Room
16-12166440	CLOSE	19-JAN-16	SERVICECALL	NAVY MESS
16-12166373	CLOSE	30-MAR-16	SERVICECALL	investigate the sulphur like smell in the west wing Press office.
16-12166365	CLOSE	14-JAN-16	SERVICECALL	landscape shop to treat for large flies in the west wing ground floor, 1st floor and 2nd floor.
16-12166186	CLOSE	10-FEB-16	SERVICECALL	WW/Plumbing Shop; see description
16-12165711	CLOSE	10-FEB-16	SERVICECALL	paint the entire stairway leading from the ground floor
16-12165693	CLOSE	11-JAN-16	SERVICECALL	To Check and Monitor the W.W. Hot Water System.
16-12165506	CLOSE	18-FEB-16	SERVICECALL	engineers to check and fix the exhaust fan the the ladies bathroom 1st floor by Roosevelt room.
16-12165117	CLOSE	25-JAN-16	SERVICECALL	WW
15-12164732	CLOSE	11-JAN-16	SERVICECALL	To Check the Water Leaking down the Wall by the Mechanical Room in the W.W
15-12164717	CLOSE	11-JAN-16	SERVICECALL	To Adjust the Temperature in the W.W. on Zone# 1W-21. - Assign to the 4 to 12 Shift Engineers
15-12164714	CLOSE	11-JAN-16	SERVICECALL	To Monitor and Adjust the W1 RO System. - Assign to the 4 to 12 Shift Enigneers
15-12164482	CLOSE	25-JAN-16	SERVICECALL	WW NO WATER
15-12164480	CLOSE	25-JAN-16	SERVICECALL	MEN'S ROOM PRESS REPAIR URINAL PARTS IN
15-12163752	CLOSE	11-JAN-16	SERVICECALL	Please have the Paint shop perform touch ups in the Oval and

FAILURECODE	ORGID	SITEID	INSPECTOR
PLUMBING	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
MOVING	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
ELEVATOR	GSA	NCR	WHUSRO
ELECTRICAL	GSA	NCR	WHUSRO
CUSTODIAL	GSA	NCR	WHUSRO
ELECTRICAL	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
MOVING	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
CUSTODIAL	GSA	NCR	WHUSRO
PLUMBING	GSA	NCR	WHUSRO
LOCKS	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
LOCKS	GSA	NCR	WHUSRO
ELECTRICAL	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
LOCKS	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
PLUMBING	GSA	NCR	WHUSRO
ELECTRICAL	GSA	NCR	WHUSRO
PLUMBING	GSA	NCR	WHUSRO
PLUMBING	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
PLUMBING	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
MOVING	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
PLUMBING	GSA	NCR	WHUSRO

MOVING	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
MOVING	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
CUSTODIAL	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
PEST	GSA	NCR	WHUSRO
CUSTODIAL	GSA	NCR	WHUSRO
MOVING	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
PLUMBING	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
PLUMBING	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
CUSTODIAL	GSA	NCR	WHUSRO
MOVING	GSA	NCR	WHUSRO
PLUMBING	GSA	NCR	WHUSRO
CUSTODIAL	GSA	NCR	WHUSRO
CUSTODIAL	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
CUSTODIAL	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
CUSTODIAL	GSA	NCR	WHUSRO
MOVING	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
MOVING	GSA	NCR	WHUSRO
MOVING	GSA	NCR	WHUSRO
MOVING	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
ELEVATOR	GSA	NCR	WHUSRO

PHYSBLDG	GSA	NCR	WHUSRO
LOCKS	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
MOVING	GSA	NCR	WHUSRO
CUSTODIAL	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
PEST	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
PLUMBING	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
MOVING	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
ELEVATOR	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
PLUMBING	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
PEST	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
CUSTODIAL	GSA	NCR	WHUSRO
PEST	GSA	NCR	WHUSRO
CUSTODIAL	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
CUSTODIAL	GSA	NCR	WHUSRO

LIGHTS	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
LOCKS	GSA	NCR	WHUSRO
ELEVATOR	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
PLUMBING	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
ELECTRICAL	GSA	NCR	WHUSRO
LOCKS	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
ELEVATOR	GSA	NCR	WHUSRO
SAFETY	GSA	NCR	WHUSRO
PLUMBING	GSA	NCR	WHUSRO
ELECTRICAL	GSA	NCR	WHUSRO
MOVING	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
SAFETY	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
CUSTODIAL	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
PEST	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
CUSTODIAL	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
CUSTODIAL	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO

MECHANICAL	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
PLUMBING	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
PLUMBING	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
PLUMBING	GSA	NCR	WHUSRO
CUSTODIAL	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
PEST	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
MOVING	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
ELECTRICAL	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
SAFETY	GSA	NCR	WHUSRO
CUSTODIAL	GSA	NCR	WHUSRO
MOVING	GSA	NCR	WHUSRO
ELECTRICAL	GSA	NCR	WHUSRO

MECHANICAL	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
PLUMBING	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
CUSTODIAL	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
CUSTODIAL	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
LOCKS	GSA	NCR	WHUSRO
PEST	GSA	NCR	WHUSRO
ELECTRICAL	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
PEST	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
CUSTODIAL	GSA	NCR	WHUSRO
CUSTODIAL	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
PEST	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
SAFETY	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO

TEMPERATURE	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
PLUMBING	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
LANDSCAPING	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
PEST	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
ELECTRICAL	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
CUSTODIAL	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
ELEVATOR	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
ELEVATOR	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO

PLUMBING	GSA	NCR	WHUSRO
LOCKS	GSA	NCR	WHUSRO
PLUMBING	GSA	NCR	WHUSRO
PEST	GSA	NCR	WHUSRO
PEST	GSA	NCR	WHUSRO
PEST	GSA	NCR	WHUSRO
SAFETY	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
ELECTRICAL	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
CUSTODIAL	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
ELEVATOR	GSA	NCR	WHUSRO
ELEVATOR	GSA	NCR	WHUSRO
PEST	GSA	NCR	WHUSRO
PEST	GSA	NCR	WHUSRO
PEST	GSA	NCR	WHUSRO
PEST	GSA	NCR	WHUSRO
SAFETY	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
PLUMBING	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
ELECTRICAL	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
CUSTODIAL	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
ELECTRICAL	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO

PHYSBLDG	GSA	NCR	WHUSRO
PLUMBING	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
ELECTRICAL	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
CUSTODIAL	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
CUSTODIAL	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
ELECTRICAL	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
PEST	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO

PAINTDAMAGE	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
ELECTRICAL	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
PLUMBING	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
LOCKS	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
PEST	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
LOCKS	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO

TEMPERATURE	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
PLUMBING	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
MOVING	GSA	NCR	WHUSRO
SAFETY	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
LIGHTS	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
PLUMBING	GSA	NCR	WHUSRO
PHYSBLDG	GSA	NCR	WHUSRO
MOVING	GSA	NCR	WHUSRO
FIRE SHOP	GSA	NCR	WHUSRO
PEST	GSA	NCR	WHUSRO
PLUMBING	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
SAFETY	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
TEMPERATURE	GSA	NCR	WHUSRO
MECHANICAL	GSA	NCR	WHUSRO
PLUMBING	GSA	NCR	WHUSRO
PLUMBING	GSA	NCR	WHUSRO
PAINTDAMAGE	GSA	NCR	WHUSRO